



Remove resistors R46,47
when using XTAL



Hole_3,8mm,WP,1

Design:	Stepper_Motor_V1_0	Rev:	V1.0
Page Description:	MAINPAGE		
Document No:	Page: 2 of 6		
File:	Date: 13/04/2012		