



PLEASE CUT MALE ELECTRODE FROM PLATE
SPARK GAP ADDED

M5 MOUNTING HOLE
2 OFF DIA 3.2 HOLES IN ELECTRODE